



Activate the 3D pdf and use the tools to spin, measure, and examine the virtual cut.

A top, bottom, and right view is preset under the views dropdown menu.

If you cannot activate the 3d pdf by clicking on the image then you need to change your web browser's pdf setting to adobe acrobat to view.

Foam Material 1lb EPS

Spar cuts qty2 .75 diameter

Servo wire hole qty1 .5 diameter

Note:

1. Wire will pass through the leading edge to cut the spar and servo wire holes, the space left from the kerf of the wire will be filled with .06 balsa sheet.
2. Servo pockets and leading edge slats will be machined at a later date
3. Port side wing is shown, starboard side is an exact cut but mirrored.